

Summary Report of Hazardous Waste and Sewage Spill Incidents per Water Code Section 13271

I. Petroleum Products

Date Reported*	Date Discovered	Location	Discharger	Problem	Action
		104 SAN JACINTO AVENUE, HEMET	ARCO PRODUCTS COMPANY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
12/26/2001	7/20/2001	3830 MCKINLEY STREET, CORONA	ARCO PRODUCTS COMPANY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
12/21/2001	10/5/2001	6287 DAY STREET, MORENO VALLEY	ARCO PRODUCTS COMPANY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
12/20/2001		4123 CHINO HILL PARKWAY, CHINO HILLS	ARCO PRODUCTS COMPANY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
12/21/2001		11887 MAGNOLIA AVENUE, RIVERSIDE	ARCO PRODUCTS COMPANY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
12/26/2001		690 STATE STREET, HEMET	ARCO PRODUCTS COMPANY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
12/26/2001		38440 HIGHWAY 74, RIVERSIDE/GREEN ACRES	ARCO PRODUCTS COMPANY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
12/20/2001		24181 MOULTON PARKWAY, LAGUNA HILLS	ARCO PRODUCTS COMPANY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
12/26/2001		4525 JURUPA STREET, ONTARIO	ARCO PRODUCTS COMPANY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
1/2/2002	11/11/2001	2898 RIALTO AVENUE, RIALTO	ARCO PRODUCTS COMPANY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
7/25/2001		247 40TH, SAN BERNARDINO	ARCO PRODUCTS COMPANY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
8/16/2000	8/16/2001	4040 CHAPMAN AVENUE, ORANGE	ARCO PRODUCTS COMPANY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS

*Report date is the date on the Unauthorized Release Report which is filled out by the local agency or the discharger.

Summary Report of Hazardous Waste and Sewage Spill Incidents per Water Code Section 13271

I. Petroleum Products

Date Reported*	Date Discovered	Location	Discharger	Problem	Action
2/1/1999	1/29/1999	250 DIAMOND DRIVE, LAKE ELSINORE	ARCO PRODUCTS COMPANY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
12/21/2001		17182 ARMSTRONG AVENUE, IRVINE	DAVEY ROOFING	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
10/10/2001		1313 SOUTH HARBOR, ANAHEIM	DISNEYLAND	UNDERGROUND STORAGE TANK LEAK DIESEL CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
		17495 EAGLE VALLEY ROAD, CORONA	EAGLE VALLEY ESTATES	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
10/25/2001	5/10/2000	2751 ORANGETHORPE, FULLERTON	TERMEFOROOSH PROPERTY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
12/21/2001	8/16/2001	147 BASELINE AVENUE, SAN BERNARDINO	FRENCH PROPERTY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
12/26/2001		10502 MAGNOLIA AVENUE, STANTON	G & M OIL COMPANY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
12/26/2001		6171 MANCHESTER BOULEVARD, BUENA PARK	HOUSE OF LOW RIDERS	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
12/26/2001		8221 GARDEN GROVE BOULEVARD, STANTON	IMPERIAL STATIONS	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
		3971 CERRITOS AVE, LOS ALAMITOS	MOBIL OIL CORPORATION	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
		3006 HARBOR BLVD, COSTA MESA	MOBIL OIL COMPANY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
7/23/2001	1/25/2001	3399 ADAMS ST., RIVERSIDE	MOBIL OIL CORPORATION	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS

*Report date is the date on the Unauthorized Release Report which is filled out by the local agency or the discharger.

Summary Report of Hazardous Waste and Sewage Spill Incidents per Water Code Section 13271

I. Petroleum Products

Date Reported*	Date Discovered	Location	Discharger	Problem	Action
11/16/2001	10/29/2001	5515 HOLT BLVD., MONTCLAIR	ROBERT CAMPBELL DBA MONTCLAIR GAS N WASH	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
12/21/2001	10/14/2001	25717 BASELINE RD, HIGHLAND	THRIFTY OIL COMPANY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
10/18/2001	6/19/2001	515 MAIN STREET, LAKE ELSINORE	TOSCO OIL COMPANY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
12/13/2000	11/2/1998	15931 INDIAN TRUCK TRAIL, CORONA	WILDROSE RANCH	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS
12/28/2001	3/8/2001	295 E. 40TH STREET, SAN BERNARDINO	SHELL OIL COMPANY	UNDERGROUND STORAGE TANK LEAK GASOLINE CONTAMINATED SOIL	INVESTIGATION IN PROGRESS

*Report date is the date on the Unauthorized Release Report which is filled out by the local agency or the discharger.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notif. No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
11/5/01	11/5/01	21237	City of Corona	Ontario Ave. & Vesper Circle, Corona, Riverside County	SSO	10,000	An estimated 10,000 gallons of sewage overflowed from a manhole due to construction debris. 500 gallons of the spill were contained, recovered, and returned to the operational sewer system. 9,500 gallons of the spill discharged into the local storm drain and flowed to the storm channel. The debris was cleared, the affected area cleaned up, and disinfected by the City of Corona staff.
10/28/01	10/26/01	8373	City of Fullerton	631 W. Houston Ave., Fullerton, Orange County	SSO	500	An estimated 500 gallons of sewage overflowed from a manhole due to a line blockage. The entire spill was contained and returned to the operational sewer system. The blockage was cleared and the affected area cleaned up by City of Fullerton staff.
11/15/01	11/10/00	8378	Midway City Sanitary District	Pacific & McFadden, Midway, Orange County	SSO	1,000	An estimated 1,000 gallons of sewage overflowed from a manhole due to unknown blockage. The spill could not be contained and therefore discharged into a local storm drain. The blockage was cleared, the affected area was cleaned up, and disinfected by Midway City staff.
11/16/01	11/12/01	21320	Rings Ranch Developer	Rings Ranch Road, Beaumont, Riverside County	SSO	500	An estimated 500 gallons of sewage overflowed from a private manhole due to construction debris. All 500 gallons of the spill were discharged to an undeveloped area where it percolated. The blockage was cleared and the affected area cleaned up and disinfected by a private contractor.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notif. No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
11/16/01	11/16/01	20426	Western Municipal Water District	March Air Reserve Base Treatment Plant, Riverside, Riverside County	SSO	27,000	An estimated 27,000 gallons of chlorinated secondary water overflowed from the chlorination basin due to a power loss. All of the spill was contained on the treatment plant site where it was either pumped into the reclaimed water storage pond or physically diverted into adjacent concrete lined drying beds. The power and equipment failure was repaired and the affected area was cleaned up by WMWD staff.
11/18/01	11/16/01	8259	Private Party	12891 Fairhaven, Tustin, Orange County	SSO	700	An estimated 700 gallons of sewage overflowed from a private manhole due to grease blockage. The entire spill was contained on private property, recovered, and returned to the operational sewer system. City of Tustin staff cleared the blockage and cleaned up and disinfected the affected area.
11/26/01	11/26/01	20285	City of Ontario	Hawthorne & Palmetto, Ontario, San Bernardino County	SSO	1,000	An estimated 1000 gallons of sewage overflowed from a manhole due to grease blockage. None of the spill was recovered and it flowed into a nearby storm drain. The blockage was cleared and the affected area was cleaned up by City of Ontario staff.
11/26/01	11/26/01	20305	Costa Mesa Sanitary District	2300 Placentia, Corporate Yard, Costa Mesa, Orange County	SSO	1,000	An estimated 1,000 gallons of sewage overflowed from a manhole due to a power failure. All 1,000 gallons of the spill were discharged into a local storm drain. The equipment was repaired and the affected area was cleaned up and disinfected by City of Costa Mesa staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notif. No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
11/30/01	11/30/01	20325	University of California, Irvine	Pereira & W Peltason Dr, Irvine, Orange County	SSO	4,500	An estimated 4,500 gallons of sewage overflowed from a manhole due to a grease blockage. All 4,500 gallons of the spill were discharged into a local storm drain. The blockage was cleared and the affected area cleaned up and disinfected by UC staff.
12/4/01	12/4/01	20411	City of Newport Beach	3300 Newport Blvd, Newport Beach, Orange County	SSO	5,200	An estimated 5,200 gallons of sewage overflowed from a manhole due to root blockage. Approximately 5,100 gallons of the spill were contained, recovered, and returned to the operational sewer system, while the rest of the spill discharged into a local storm drain. The blockage was cleared and the affected area cleaned up and disinfected by City of Newport Beach staff.
12/4/01	12/4/01	20412	Private Property Owner	10158 Adams Ave, Huntington Beach, Orange County	SSO	500	An estimated 500 gallons of sewage overflowed from a private lateral due to debris blockage. Approximately 200 gallons of the spill were contained, recovered, and returned to the operational sewer system, while the rest of the spill was discharged into a nearby storm drain. The blockage was cleared and the affected area cleaned up and disinfected by a Private Property Owner.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notif. No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
12/4/01	12/4/01	20425	City of Rancho Cucamonga	NE corner of Archibald & Baseline, Rancho Cucamonga, San Bernardino County	SSO	1,000	An estimated 1,000 gallons of sewage overflowed from a manhole due to a grease blockage. All 1,000 gallons of the spill were contained, recovered, and returned to the operational sewer system. The blockage was cleared and the affected area cleaned up and disinfected by City of Rancho Cucamonga staff.
12/13/01	12/13/01	21317	City of La Habra	521W. Imperial HWY, La Habra, Orange County	SSO	1,000	An estimated 1,000 gallons of sewage overflowed from a manhole due to unknown blockage. None of the spill was contained and all of it discharged into a local storm drain and flowed to Coyote Creek. The blockage was cleared and the affected area was washed, cleaned up, and disinfected by City of La Habra staff.
12/14/01	12/14/01	21218	City of Corona	1800 block of Wild Turkey, Corona, Riverside County	SSO	750	An estimated 750 gallons of sewage overflowed from a manhole due to inflow on a rainy day. The sewer line could not handle the volume of the rain water. All 750 gallons of the mixed sewage and the rain water discharged into a local storm drain. The capacity of the sewer line is being addressed by the City of Corona.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notif. No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
12/15/01	12/15/01	21318	Private Party	21372 Brookhurst, Huntington Beach, Orange County	SSO	6,041	An estimated 6,041 gallons of sewage overflowed from a private manhole due to a grease blockage. 5,823 gallons of the spill were contained, recovered, and returned into the operational sewer system. 218 gallons of the spill were not recovered and discharged to the local storm drain. The blockage was cleared and the affected area cleaned up and disinfected by a private contractor with assistance of Huntington Beach staff.
12/17/01	12/17/01	8380	City of Garden Grove	Edinger & Newhope, Fountain Valley, Orange County	SSO	500	Approximately 500 gallons of sewage overflowed from a manhole due to a line blockage. An estimated 450 gallons of the spill were contained, recovered, and returned to the operational sewer system, while the rest of the spill was discharged into a local storm drain. City of Garden Grove staff cleared the blockage and cleaned up and disinfected the affected area.
12/23/01	12/23/01	8303	Private Party	3150 W. Lincoln Ave., Anaheim, Orange County	SSO	500	An estimated 500 gallons of sewage overflowed from a manhole due to a grease blockage. All 500 gallons of the spill were contained in a parking lot of a shopping center, recovered, and returned into Operational sewer system. The blockage was cleared and the area cleaned up and disinfected by City of Anaheim staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notif. No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
12/23/01	12/23/01	8308	City of Anaheim	2173 W. Lincoln Ave., Anaheim, Orange County	SSO	1,500	An estimated 1,500 gallons of sewage overflowed from a manhole due to a blockage caused by an unknown person forcing rags and grease into the sewer line. All of the spill discharged into a local storm drain and entered the Santa Ana River. City of Anaheim staff cleared the blockage and cleaned up the affected area and vacuumed the storm drain.
12/28/01	12/13/01	8524	City of Newport Beach	Big Canyon Country Club, Newport Beach, Orange County	SSO	1,500	An estimated 1,500 gallons of sewage overflowed from a private manhole due to a line blockage at Big Canyon Country Club. The entire spill was contained on the golf course, recovered, and returned to the operational sewer system. City of Newport Beach staff cleared the blockage and cleaned up the affected area.
12/28/01	12/23/01	8251	City of Anaheim	2173 W. Lincoln, Anaheim, Orange County	SSO	1,500	An estimated 1,500 gallons of sewage overflowed from a manhole due to a grease blockage. None of the spill was recovered, and was discharged into a local storm drain. The line blockage was cleared and the affected area cleaned up and disinfected by City of Anaheim staff.
12/28/01	12/27/01	8247	City of Santa Ana	1508 St. Andrews, Santa Ana, Orange County	SSO	1,500	An estimated 1,500 gallons of sewage overflowed from a manhole due to a construction debris blockage. The entire spill was contained, recovered, and returned into the operational sewer system. The blockage was cleared and the affected area cleaned up and disinfected by City of Santa Ana staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notif. No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
12/28/01	12/27/01	8254	Private Party	1461 Foothill Blvd, Tustin, Orange County	SSO	1,000	An estimated 1,000 gallons of sewage overflowed from a manhole due to a grease blockage. The entire spill was contained, recovered, and returned into the operational sewer system. The blockage was cleared and the affected area cleaned up and disinfected by the City of Tustin staff.